
VTT BUILDING TECHNOLOGY

TEST REPORT NO. RTE10537/99

Determination of impact sound insulation

Tuplex





BUILDING TECHNOLOGY

Requested by

Tupler Oy

Suonsivunkatu 14 FIN-33420 Tampere

Order

Klaus Gummerus, telefax 12.10.1999

TEST REPORT

Contact person at VTT

Reijo Heinonen

VTT Building Technology

Air Handling Technology and Acoustics

P.O. Box 1804 FIN-02044 VTT

Tel. + 358 9 456 6984 Fax. + 358 9 456 4709

Task

Determination of impact sound insulation

Sample

Parquet underlay was delivered by the customer for impact sound insulation measurements with parquet strips. The following information of the sample was reported by the customer:

Name:

TUPLEX

Type:

3 mm parquet underlay - expanded polystyrene

grains 2-4 mm between plastic foils

Manufacturer:

Tupler Oy, Finland

Parquet strips:

14 mm oak

- width x height:

188 x 2526 mm

- area:

 12 m^2

- mass per unit area:

 7.7 kg/m^2

Mounting and measuring

VTT glued the parquet strips according to the manufacturers instruction together to accomplish a floating floor, which was mounted on to the concrete testing slab. The parquet underlay was mounted below the parquet strips. Weights $(1\ 200\ kg = 100\ kg/m^2)$ were lied on the sample during the measurements. The tapping machine was situated on 10 different measurement locations. The impact sound pressure levels were measured in the reverberation room below the test floor using moving microphones. After removing the sample, the same measurements were made again on the bare concrete floor.

The sample was received:

17 March 1998

Gluing of parquet strips (PVAC glue): 17 March 1998

Loading and measurement:

20 March 1998



Methods and equipment

The normalized impact sound pressure level L_n and the reduction of sound pressure level (improvement of impact sound insulation) ΔL were measured according to the standards ISO 140-6:1998 [1] and ISO 140-8:1997 [2]. The single-number quantity for the sample ΔL_w is calculated according to ISO 717-2:1996 [3].

The construction thicknesses of the concrete walls and floors of the reverberation room are 0.25 m. The floor dimensions are 4.70 m and 5.80 m and the height is 3.70 m. The volume is 102 m³. The dimensions of the concrete test slab are 3.00 m and 4.00 m and thickness is 190 mm.

In the standard the recommendated thickness of the test slab is 100-160 mm and the uniformly distributed load is 20-25 kg/m² [2].

Measuring equipment:

B&K (Brüel&Kjær) 4166
B&K 2639
B&K 3923
Yamaha MX-1000
Sinmarc V121L
Norsonic 830
B&K 4220
B&K 3204

Results

The reduction of impact sound pressure level ΔL in third octave bands are shown in Appendix 1. The weighted reduction of impact sound pressure level $\Delta L_{\rm w}$ is 18 dB.

The measured improvement values in third octave bands have been subtracted from impact sound levels of some typical concrete bare floors in practice: three massive concrete slabs and three hollow core slabs. The sound level values of the concrete floors are given in finnish sound isolation instructions [4].

The weighted normalized impact sound indices $L'_{n,w}$ were calculated for floor slabs (when the floating sample is in place) according to the standard ISO 717-2:1996.

The weighted normalized impact sound pressure levels $L'_{n,w}$ for different types of the slabs and the weighted reduction of impact sound pressure level ΔL_w are presented in Table 1.

These results are based on tests made with a standardised tapping machine in laboratory conditions.

The results of the measurement are valid only for the measured sample.

Table 1. The weighted reduction of impact sound pressure level $\Delta L_{\rm w}$ and the approximated weighted normalized impact sound pressure level $L'_{\rm n,w}$ for concrete slabs 160, 190 and 210 mm and for hollow core slabs 250-300, 300-375 and >375 kg/m². The hollows have a circle or slightly elliptical shape. The volume of the room below the test floor is at most 50 m³. ISO 140-6:1998, ISO 140-8:1997 and ISO 717-2:1996.

slab floor covering	160/190/210 ML L' _{n,w} [dB]	250/300/375 OL L' _{n,w} [dB]	ΔL _w [dB]
Parquet 14 mm and parquet underlay: Tuplex (load 100 kg/m²)	56/54/53	56/54/52	18

Espoo, 31 December 1999

Juhani Parmanen

Chief Research Scientist

Reijo Heinonen

Research engineer

References

[1] ISO 140: Acoustics - Measurement of sound insulation in buildings and of building elements - Part 6:1998: Laboratory measurements of impact sound insulation of floors

[2] ISO 140 - Part 8:1997: Laboratory measurements of the reduction of transmitted impact noise by floor coverings on a heavyweight standard floor [3] ISO 717: Acoustics - Rating of sound insulation in buildings and of building elements - Part 2:1996: Impact sound insulation

[4] Suomen Rakentamismääräyskokoelma: C5 - Ääneneristys - Ohjeet 1985

Appendix 1

Results of the measurement

Distribution

Customer VTT

2 Originals
Original



Product:

Manufacturer:

Parquet 14 mm and parquet underlay Tuplex

Tuplex: Tupler Oy, Tampere

Reduction of impact sound pressure level

Measurement: Rating:

ISO 140-8:1997 ENISO1408:1997

ISO 717-2:1996 ENISO7172:1996

Date of test:

20 March 1998

Test slab:

Concrete190 mm

Mass per unit area:

Curing time:


Air temp. in the source room: Air humidity in the source room:


Receiving room volume:

kg/m² h

20 °C 19 %

Frequency range for rating according to ISO 717-2





Rating according to ISO 717-2:

5000

18 dB;

C 1,r,50-2500

= 0 dB

These results are based on tests made with a tapping machine under laboratory conditions.

for beun